Executive Engineer, Construction Divison No.3,
P. W. D. (B&R) Br., Batala Road, Amritsar

To

The Principal,
Bibi Kaulan ji Public School,
Near Gurdwara Tahla Sahib,
Tarn Taran Road,
Distt. Amritsar.

No. 3293 Dated: 18-11-2026

Subject: **Building Safety Certificate for the year 2026 to 2027.**
(Bibi Kaulan ji Public School, Near Gurdwara Tahla Sahib, Tarn Taran Road District Amritsar)

Ref: Your office letter No.BKJ/6257/26 Dated 13.08.2026

Sub Divisional Engineer, Construction Sub Division No.6, PWD (B&R) Br., Amritsar, vide his office letter No.363 dated 17.11.2026 has reported this office that the building of "**(Bibi Kaulan ji Public School, Near Gurdwara Tahla Sahib, Tarn Taran Road District Amritsar)**" has been visually inspected and found fit for human inhabitation for One years 2026-27 i.e. upto 31.03.2027.

DA/Performa I & II.

Executive Engineer,
Consruction Division No.3,
P.W.D. (B&R) Br., Amritsar.

Endst.No._____ Dated:_____

A copy of above is forwarded to Sub Divisional Engineer, Construction Sub Division No.6, PWD (B&R) Br., Amritsar w.r.t. his letter No.363 dated 17.11.2026 for information and necessary action.

D.A./Nil

Executive Engineer,
Consruction Division No.3,
P.W.D. (B&R) Br., Amritsar

Annexure D

BUILDING SAFETY CERTIFICATE

No. Dated: .....

It is certified that the existing building ..Bibi....Kaurlenji.....bublic School ...(name of the building or premises) at .....Near Gurdwara Baba Tara Taraj.... Road ASR

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	G+1	G+1	G+1		

The building is owned/occupied by.Bibi...Kaurlenji Public School Tahli Sahib (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of S.D.E...Constn. Dn. 6 (Name of Department/ Govt.) on..12-11-2026...(date of inspection) in the presence of ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from.12-11-26. for a period of .31-03-2027 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Clean at toilets premises Safe Road Sign
2. Smoke mountain in Mandatory
3.
4.

Issued on ..... at ..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : Sub Divisional Engineer, Construction Sub Divn No. 6, PWD B&R Br., Amritsar.

Name :

Designation :

Name & Address of Department/ Office: _____

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

(PART-1)

(To be filled in by the head of school, institute)

1. Name of the School — Bibi Kaulan ji Public School
2. Location — Near Gurdwara Tehla Sahib, TT Road, ASR
3. Plot Area — 14400 Sq yards (12040 Sq Mtr)
4. Covered Area of Building — 75594.85 Sq. Ft
5. Number of Stories — 4 Storey's
6. Year of Construction — 2 Floors (2010)
   (a) Frame Structure — RCC Structure
   (b) Brick Masonry structure — 4" & 9" walls in Brick Masonry Structure
7. If the building has been constructed under the supervision of the qualified engineer, the following details may be given:-
   a) Name of Engineer with qualification — Sukhmander Singh (Civil Engg)
   b) Address of the Engineer — SCO-123, B-Block -5th Floor
   c) If structural drawing used in the construction, if available? — Yes
   d) Name and address of Architect with qualification — As above

8. Whether the building has been constructed for the purpose of
   a) School — ✓ Yes/No
   b) Residential purpose and used for a school — Yes/No

9. Materials used for Roofs
   a) R.C.C. Slabs — R.C.C Slabs
   b) R.S.Joists & Battons
   c) Wooden Joints and bottom

10. Material used for Walls
    a) Mud Motror — Yes/No
    b) Cement Motor — ✓ Yes/No
    c) Lime Mortor — Yes/No

11. Flooring
    a) Conglomerate — ✓ Yes/No
    b) Terrace — Yes/No
    c) Brick Paving — Yes/No

12. A detailed drawing indicating the doors along with windows and location fitting and windows is attached.

13. FOR FIRE SAFETY

a) Whether the width of the staircase is 1.5 mtr. Yes/No
b) Whether portable fire extinguisher exists Yes/No
e) Whether School building is free from inflammable & & toxic material Yes/No
di Whether cooking of food is done at a sate place Yes/No
e) Whether any Thatch or combustible material has bee used Yes/No

14 Requirement for Fire Protection Arrangements under NB-Part-IV

(For Building height less than 15 metre)

a) Whether Hose Real provided Yes/No
b) Whether down comer provided Yes/No
c) Whether Automatic sprinkler provided Yes/No
d) Whether underground static water storage tank of capacity 50000 Ltr. (if converted area exceeds 1500 sqn) Yes/No
e) Whether over head tank of capacity 10000 Ltr.exists (in case of hose real) 20000 Ltr. Yes/No
f) Whether one eclectic and one diesel pump of 3 kg/cum Pressure of capacity 1620 LPM. one electric pump of Capacity 180 LPK exist near underground static tank. Yes/No
g) Whether a pump 3 kg/cum pressure & 450/500 LPM Exist near over head tank. Yes/No

Signature of the Head of School/ Institute

Principal
Bibi Kaulan Ji Public School (Senior Secondary)
Nr. Gurdwara Tahla Sahib, Tarn Taran Road,
Amritsar, Affiliated to CBSE Vide No. 1630704

PART-II

(To be filled by the SDE of PWD (B&R) Department)

a) I have visited the above mentioned school on dated _____and have visually inspected it from all angles of safety and find it fit for normal use as school building.
b) In case any addition/alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
c) In case the building is affected by flood, or if there is settlement of walls/foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
(d) This building can be safely occupied for normal use upto (indicate upto which it can be used) Building is Visually Safe upto 31.3.17

Sub Divisional Engineer,
Construction Sub Divn No. 6,
PWD B&R Br., Amritsar.